4. Revise the bay at the entrance door by removing the wrought iron rail indicated over the bay, and narrowing the extension down from 2'-10" to 3", at a maying of

6 450,00

- - bobnemenoer gulvas Lator

\$ 6,983.00

Your Cormittee considered other suggested changes, but these are the only ones which we could recommend to you, and it is our belief that none of these changes will in any way affect the usofulness of this structure.

We recommend to you the adoption of those changes.

You will note that Mr. Howsen is a member of our Committee, and that his signature does not appear on this report. We, however, have a letter from him, which we will be glad to show to any member of Council, concurring in general in these changes.

Respectfully submitted: