

- ★ CLEANOUT
- MANHOLE
- CEMENT LINE
- NEW MANHOLE
- + REBUILD INVERT
- WT F&C
- CAM LOCK WT F&C
- ◇ SPECIAL, SEE NOTES AND WORKLIST
- CIPP
- BURST

0 50 100 150 200 400 Feet

04C-0040.0
DID NOT RECEIVE
CAM LOCK WT F&C
04C-0040.3 DID GET
CAM LOCK WT F&C

SHEET 3



LATERALS TO BE REINSTATED OR GROUTED
ARE NOT SHOWN ON THE PLANS. ALL WORK
ON THIS SHEET IS IN ROANOKE COUNTY.

Drawing Copyright © 2011

1116 South Main Street • Blacksburg, VA 24060-5548
Main: (540) 552-5548 • www.ciacompanies.com

Draper Aden Associates

Engineering • Surveying • Environmental Services

Blacksburg, VA
22904 South Main Street
Blacksburg, VA 24060
540-552-5548 • www.daa.com

ORLANDO AVENUE
(VISTA AREA)

**WESTERN VIRGINIA
WATER AUTHORITY**

**FY2011 VCWRLF COLLECTION
SYSTEM PROJECTS**

CONTRACTS 1A & 1B REHABILITATION

DESIGNED BY:	JSB
DRAWN BY:	CDH
CHECKED BY:	DBH
SCALE:	AS SHOWN
DATE:	FEB 2012
PROJECT NUMBER:	23184

SHEET 4