

ITEM CODE	MANHOLE NUMBER	ТУРЕ	TOP ELEVATION (FT)	PIPE INVERT IN (FT)	PIPE INVERT OUT (FT)	DEPTH (FT)	REQUIRED REHABILITATION * Rehab MH per Section 02737	
F	12B-0064	BRICK WITH PRECAST UPPER	1006.1	995.9	995.8	10.3		
G	12A-0063	PRECAST UNIT	1006.68	994.51	994.41	12.3	Rehab MH per Section 02737	
Н	12A-0062	PRECAST UNIT	1007.55	993.5	993.4	14.2	Rehab MH per Section 02737	
1	12A-0061	PRECAST UNIT	1004.39	992.34	992.24	12.2	Rehab MH per Section 02737 Install Vent	

* INSPECTOR MUST APPROVE ALL MANHOLE PREPARATION PRIOR TO ANY REHABILITATION WORK AND/OR FINISHED PRODUCT INSTALLATION.

CODE	MAIN MATERIAL	DIAMETER (IN)	UPSTREAM ELEVATION (FT)	DOWNSTREAM ELEVATION (FT)	LENGTH (FT)	SLOPE (%)
6	CONCRETE	24	995.8	994.51	213	0.61
7	CONCRETE	24	994.41	993.5	248	0.37
8	CONCRETE	24	993.4	992.34	258	0.41

NOTES

- LIMITS OF WORK THIS SHEET PERTINENT TO VEHICULAR EQUIPMENT ACCESS AS REQUIRED
 TO PERFORM THE REHABILITATION WORK AND/OR ROUTE OF WER DYPAGO PIPING.
- 2. CONTRACTOR SHALL SWEEP THE GREENWAY CLEAN AT THE END OF EACH WORK DAY.
- CONTRACTOR MAY ACCESS MANHOLES OUTSIDE OF LIMITS-OF-WORK VIA FOOTPATH ONLY.
 NO VEHICLE TRAFFIC OUTSIDE OF LIMITS-OF-WORK IS ACCEPTABLE.
- 4. IT SHALL BE UNDERSTOOD AND AGREED UPON BY THE CONTRACTOR THAT ONLY THOSE TREES THAT DIRECTLY INTERFERE WITH THE CONSTRUCTION OF THE WORK MAY BE REMOVED. WITHIN THE LIMITS OF WORK TREES FOR MCHES (4) FOR MANTEER AND SMALLER MAY BE REMOVED. NO TREE GREATER THAN FOUR MCHES (4) FOR MANTEER AND SMALLER MAY BE REMOVED. THE OFFICE AND THE OWNER ALL LOST ASSOCIATED WITH CLEARNING FOR SIDE OF THE APPROVAL OF THE OWNER ALL LOST ASSOCIATED WITH CLEARNING FOR SIDE OF THE APPROVAL OF THE OWNER ALL LOST ASSOCIATED WITH CLEARNING FOR SIDE OF THE APPROVAL OF THE OWNER ALL LOST ASSOCIATED WITH CLEARNING FOR SIDE OF THE APPROVAL OF THE OWNER ALL LOST ASSOCIATED WITH CLEARNING FOR SIDE OF THE APPROVAL OF THE OWNER ALL LOST ASSOCIATED WITH SIDE OWNER ALL SIDE OWNER ALL SIDE OWNER ASSOCIATED WITH SIDE OWNER ALL SIDE OWNER ASSOCIATED WITH SIDE OWNER ALL SIDE OWNER ASSOCIATED WITH SIDE OWNER ASSOCIATED WITH SIDE OWNER ALL SIDE OWNER ASSOCIATED WITH SIDE OWNER ASSO



LICK RUN INTERCEPTOR REHABILITATION



601 South Jefferson St. Suite 300 Roanoke, VA 24011 540.853.5700 tel 540.283.8212 tax www.westernvawater.org

CONSULTANT

AECOM 10 3. Jefferson St. Salte 1000 Roanoke, VA 24011 540.857.3100 tel 540.857.3180 fax www.aecom.com

REGISTRATION



ISSUE/REVISION

VR DATE DESCRIPTION

PROJECT NUMBER 60505031

SHEET TITLE

SANITARY SEWER REHABILITATION PLAN STATION 28+50 TO STATION 36+50

SHEET NUMBER

GRAPHIC SCALE