





6/15/2011 G:\2011-SDE\Jobs\1821007_00-Carvins Cove Dam Break Analysis\GIS\CC_Panels.mxd



- Cross Section
- Stream
- Spillway Design Flood
- Sunny Day Breach
- Spillway Design Flood With Breach



Distance from Dam
(miles)

Cross Section

First Flood Waters^a
Cross Section DD 28.8

Peak Flood Level^a
(hr:min) 3:30

Depth of Water^{**}
(feet) 63.5

Sunny Day Dam Breach

First Flood Waters^a
Cross Section EE 30.5

Peak Flood Level^a
(hr:min) 3:35

Depth of Water^{**}
(feet) 74.9

Spillway Design Flood Breach

First Flood Waters^{**}
Cross Section EE

Peak Flood Level^a
(hr:min) 20:19

Depth of Water^{**}
(feet) 64.8

First Flood Waters^{**}
Cross Section DD

Peak Flood Level^a
(hr:min) 20:20

Depth of Water^{**}
(feet) 75.8


Notes:

- The information contained in this map is prepared for use in notification of downstream property owners by emergency management personnel.
- Mapping of flooded areas and floodwave travel times are approximate. Timing and extent of actual inundation may differ from information presented on this map.
- It is prudent to assume that areas outside, but adjacent to, the inundation limits shown could also be flooded.
- Due to the topography, floodwave similarities, and map scale, inundation lines may obscure other inundation lines at some locations on the map.
- Hazard Potential Classification: HIGH
- Spillway Design Flood: Probable Maximum Flood
- The dam's hazard potential classification information shown in this map documents the conditions at the time the map is signed and printed.
- The impacted addresses shown on the map are a result of the Spillway Design Flood with Breach.
- Dam break inundation zone maps shall be provided by the owner to the local government for use in review of proposed development plans and zoning.


*Start time is the beginning of the breach.
** Start time is the beginning of the storm.
*** Depth of water above channel bottom.

0 600 1,200 2,400
Feet
Coordinate System: NAD 1983 StatePlane Virginia 3 FIPS 4502
Source: Virginia Geographic Information Network (2009)
Aerial Imagery Copyright 2002 Commonwealth of Virginia (2009)
ESRI MediaKit (2010)

© Schnabel Engineering, 2011 All Rights Reserved



DESIGNED BY: MRG	DRAWN BY: GAN	CHECKED BY: ANG	DATE
ANTHONY W. GRUBBS, P.E. DATE 6/24/11			
VIRGINIA PROFESSIONAL ENGINEER NUMBER 046668			



Schnabel
ENGINEERING

11A OAK BRANCH DR / GREENSBORO NC 27407
T: 336.224.4546 F: 336.224.4547

CARVINS COVE DAM BREACH ANALYSIS
DAM BREAK INUNDATION ZONE MAP
BOTETOURT COUNTY, VA

PANEL 9

DRAWING NO:
1821007.00
SHEET:
10 OF 10