




3014 - Lid has holes
3015 - Lid has holes

Taped 5.12.17-Disc 4
side B



IS - VCL-ICI OF L-IEF-ICI -I PERFECT, UTLESS -E- -FE
 IS - VCL-ICI OF L-IEF-ICI -C. UICSEI PROFESSION-LIS
 EICIEFIC -FCHIECI, L-IESC -FCHIECI OF L-IE
 EIC-ICI -C L-IEF -I IEL II -I -I -I -I IEL BE-FIC
 E-SIC -C - UICSEI PROFESSION-LIS -LIEFED, E
 EICIEFIC EICIEFIC -FCHIECI, L-IESC -FCHIECI OF
 L-IE SURVEYER-SHALL SIC-IE EICIEFIC
 EICIEFIC EICIEFIC -LIEFED E- FOLLOWED E- IEF
 ICI -IURE, E-IE C-IE SIC -LIEF-ICI, -C - SPECIFIC
 DESCRIPTION OF E- LIEF-ICI.

	Submittal/Revision	App'd.	By	Date
	Bid Issue	DBH	KJV	10/07/16
	50% Submission	DBH	KJV	05/12/16

CONTRACT 1 -
016 SANITARY SEWER REHABILITATION

Completed 5.31.17
17th Street

Designed By: KJV	Project No: 31237	Drawing No.: C-124
Drawn By: KJV	Scale: AS SHOWN	
Checked By: DBH	Issue Date: October 2016	

● Sanitary Manhole
 — Sanitary Sewer

Sanitary Sewer Rehabilitation

Line
Burst

● Capped- Do Not Reinstate

 Replace

■ ■ ■ Replace - Pavement

Trim and Replace

- Trim and Replace - Pavement

 Trim - Do Not Reinstate

Assist Owner to Verify
Active - Replace if Active

 Verify Active - Pavement

Existing PVC - Reconnect
at Sewer Main

 Existing PVC - Pavement -
Reconnect at Sewer Main

 Install Water-Resistant F&C

 Reseal Existing Frame

 Install Standard F&C

 Seal Chimney

 Cementitious Line Manhole

- ✱ Repair Crack/Holes in Wall

✚ Seal Pipe Connections

 Seal Wall/Bench Connection

- ✱ Repair Crack/Holes in Bench

 Install 8-inch Cleanout

CP = Concrete Pipe

VCP = Vitrified Clay Pipe

