

4119 - where is CO? [Uncovered]



ROANOKE, VIRGINIA
3164 has H₂O-tight lid

COMMONWEALTH OF VIRGINIA
DOUGLAS B. HUDGINS
Lic. No. 034694
10/01/16
PROFESSIONAL ENGINEER
(Begins side B)

IT IS - NCL-INT OF L-V-FCR -I- PERFCT, UNLESS THE -
-CHNG I-FCR THE DEFECTIC -C- LICENSED PROFESSIONAL
-EIGENRHO, -PCHIEC I, L-TSC-FC -PCHIEC C L-M
SUPERVOR IC -LIER -I- IEL II -I- V-FC -I- IEL RE-FC
THE SI-L-FC C- LICENSED PROFESSIONAL IS -LIERED, THE
-LIERIG EIGENRHO, -PCHIEC I, L-TSC-FC -PCHIEC I
L-TD SUPERVOR SH-LL SI-L-FC THE OCCUEN I
-I- INCLUDE THE I-CH-INT, -LIERED -I- FOLLOWED BY THE
SIGI -I-RE, THE -I-IE OF SUCH -LIER-INT, -I- A SPECIFIC
DESCRIPTION OF THE -LIER-INT.

No.	Submittal/Revision	App'd.	By	Date
-	Bid Issue	DBH	KJV	10/07/
A	50% Submission	DBH	KJV	05/12/

CONTRACT 1 -
2016 SANITARY SEWER REHABILITATION

New line laterals installed by Midas
Morehead Street
7.14-7.19.17

Designed By: KJV	Project No: 31237	Drawing No.: C-132
Drawn By: KJV	Scale: AS SHOWN	
Checked By: DBH	Issue Date: October 2016	

Pipe Material Legend

CP = Concrete Pipe

VCP = Vitrified Clay Pipe



./\Projects\BVA\31237\Data\GIS\100% Construction Drawings-Updated.mxd

