

CODE	MVWA MANHOLE NUMBER	TYPE	TOP ELEVATION (FT)	PIPE INVERT IN (FT)	PIPE INVERT OUT (FT)	DEPTH (FT)	REQUIRED REHABILITATION *
N	12A-0056	PRECAST UPPER	993.59	987.79	987.69	5.9	Rehab MH per Section 02737, Replace Frame & Cover
0	12A-0055	BRICK WITH PRECAST UPPER	993.63	986.18 (24" N) 989.43 (8" E)	986.08	7.5	Rehab MH per Section 02737

ECTOR MUST APPROVE ALL MANHOLE PREPARATION PRIOR TO ANY REHABILITATION WORK AND/OR FINISHED PRODUCT INSTALLATION.

CODE	MAIN MATERIAL	DIAMETER (IN)	UPSTREAM ELEVATION (FT)	DOWNSTREAM FLEVATION (FT)	LENGTH (FT)	SLOPE (%)
13	CONCRETE	24	989.14	987.79	256†	0.53
14	CONCRETE	24	987.69	986.18	345	0.44
15	CONCRETE	24	986.08	985.19	318†	0.28

TABLE NOTE:

† LENGTH INDICATED IS MANHOLE TO MANHOLE DISTANCE. SEWER MAIN TRAVERSES ACROSS MULTIPLE SHEETS.

Last saved by: BETH: PRESLEY(2018-01-17) Last Plotted: 2018-01-18 Filename: U:80505031 - LICKRUN INTERCEPTOR REHABILITATION(90)

NOTES:

LIMITS OF WORK THIS SHEET PERTINENT TO VEHICULAR EQUIPMENT ACCESS AS REQUIRED TO PERFORM THE REHABILITATION WORK AND/OR ROUTE SEWER BYPASS PIPING.

Shot 9

- CONTRACTOR MAY ACCESS MANHOLES OUTSIDE OF LIMITS-OF-WORK VIA FOOTPATH ONLY. NO VEHICLE TRAFFIC OUTSIDE OF LIMITS-OF-WORK IS ACCEPTABLE.
- LATERAL LINE MOT CONNECTED TO UPSTREAM MANIFOLE, GINGE NO INVERT ELEVATION COULD BE FOUND, SLOPE ASSUMED TO BE 2%, SIZE AND LENGTH OF LATERAL PER WWWA GIS.
- 4. CONTRACTOR SHALL OWEEP THE GREENWAY CLEAN AT THE END OF EACH WORK DAY.
- ET FEHALLER UNICCEPTOGO AND ARREST DEVINEY THE CONTRACTOR THAT CAN'T TAGE
 TRESS THAT THORSELY MITTERES WITH THE CONTRACTOR THAT CAN'T TAGE
 REMOVED, WITHIN THE LIBRIT OF WORK, HEEDS HOUN RULESS (4) BU DAMETER AND
 SMALLERAMY BE REMOVED. NO TREE GREATER THAN FOUR NICHES (4) BU DAMETER AND
 WITH CLEARING GRUBBING, STE CLEARING, AND TREESHOUB REMOVAL, SMALL RE
 WITH CLEARING GRUBBING, STE CLEARING, AND TREESHOUB REMOVAL, SMALL RE

GRAPHIC SCALE

AECOM

LICK RUN INTERCEPTOR REHABILITATION



601 South Jefferson St. Suite 300 Roanoke, VA 24011 540.853.5700 tel 540.283.8212 fax www.westernvawater.org

CONSULTANT

AECOM 10 S. Jefferson St. Suite 1600 Roanoke, VA 24011 540.857.3180 fax www.secom.com

REGISTRATION



+		
+	-	
I/R	DATE	DESCRIPTION

PROJECT NUMBER

60505031

SHEET TITLE

SANITARY SEWER REHABILITATION PLAN STATION 44+25 TO STATION 52+00

SHEET NUMBER