

CODE	WVWA MANHOLE NUMBER	TYPE	TOP ELEVATION (FT)	PIPE INVERT IN (FT)	PIPE INVERT OUT (FT)	DEPTH (FT)	REQUIRED REHABILITATION *
w	12A-0047	BRICK	987.98	973.78 (24" NW) 986.11 (8" NE)	973.68	14.3	Rehab MH per Section 02737 Replace Frame & Cover
×	12A-0046	PRECAST UNIT	980.03	9/3.48	9/3.38	6.6	Remove Fx Chimney Seal, Rehab MH per Section 0273
٧	174.0045	BRICK	983.64	972.64 (24" NW) UNKNOWN (6" NE) UNKNOWN (6" SW)	972.54	11.1	Rehab MH per Section 02737 Install Vent
Z	12A-0044	PRECAST UNIT	978.87	972.42	972.32	6.5	Rehab MH per Section 0273
AA	12A 0043	PRECAST UNIT	978.4	972.3	972.2	0.2	Rehab IVIH per Section 0273

\* INSPECTOR MUST APPROVE ALL MANHOLE PREPARATION PRIOR TO ANY REHABILITATION WORK AND/OR FINISHED PRODUCT INSTALLATION.

CODE	MAIN MATERIAL	DIAMETER (IN)	UPSTREAM ELEVATION (FT)	DOWNSTREAM ELEVATION (FT)	LENGTH (FT)	SLOPE (%)
23	RCP CLASS III	24	973.68	973.48	183	0.11
24	RCP CLASS III	24	973.38	972.64	263	0.28
25	RCP CLASS III	24	972.54	972.42	114	0.11
20	KCP CLASS III	24	9/2.32	972.3	39	0.05

## NOTES:

- LIMITS OF WORK THIS SHEET PERTINENT TO VEHICULAR EQUIPMENT ACCESS AS REQUIRED TO PERFORM THE REHABILITATION WORK AND/OR ROUTE SEWER BYPASS PIPING.
- 2. INFORMATION PERTINENT TO NOTED BRANCHING MANHOLES, LATERALS AND MAINS BASED ON WWWA GIS INFORMATION, CONTRACTOR SHALL FIELD VERIFY.
- LATERAL LINE NOT CONNECTED TO UPSTREAM MANHOLE. SINCE NO INVERTICLEVATION COULD BE FOUND, SLOPE ASSUMED TO BE 2%, SIZE AND LENGTH OF LATERAL PER WWWA GIS.
- NOTED MANIFOLE LOGATED OFF PLAN SHEET, LINEAR DISTANCE AND OTHER INFORMATION RELEVANT TO THE MANHOLE BASED ON WWWA GIS DATABASE, CONTRACTOR SHALL FIELD VERITY;
- 5. CONTRACTOR SHALL SWEEP THE GREENWAY AT THE END OF EACH WORK DAY.
- CONTRACTOR MAY ACCESS MANHOLES OUTSIDE OF LIMITS-OF-WORK VIA FOOTPATH ONLY. NO VEHICLE TRAFFIC OUTSIDE OF LIMITS-OF-WORK IS ACCEPTABLE.
- 7. IT CHALL BE UNDERSTOOD AND ADDRED UPON BY THE CHATRACTER THAT CAN'T THOSE THRES THAT THOSE THRES THAT THOSE OF THE CHATRACTER THAT CAN'T THOSE THRES THAT THE CHATRACTER OF THE THAT CHATRACTER OF THE CHATRA



## **AECOM**

PROJEC

LICK RUN INTERCEPTOR REHABILITATION

CLIENT



601 South Jefferson St. Suite 300 Roanoke, VA 24011 540.853.5700 tel 540.283.8212 fax www.westernyayeter.org

CONSULTANT

AECOM 10 S. Jefferson St. Suite 1600 Roanoke, VA 24011 540.857.3100 tel 540.857.3180 fax www.oecom.com

REGISTRATION



+	100	
	1	
$\pm$		

PROJECT NUMBER

60505031

SHEET TITLE

SANITARY SEWER REHABILITATION PLAN STATION 67+75 TO STATION 75+50

SHEET NUMBER

C109