



Diagram illustrating the Tree Planting Detail, showing a cross-section of a tree trunk and root system. The diagram includes labels for various components:

- 1. SPRAY WITH ANTI-DESICCANT PRIOR TO DELIVERY
- 2. PRUNE DEADWOOD TREES APPROX. 1/3 OF BRANCHES
- 3. 1/2" MIN. GARDEN HOSE
- 4. 3"-8" GALVANIZED TURNBUCKLES
- 5. 12 GAUGE TWISTED GALVANIZED WIRE DOUBLE STRAND
- 6. TREE WRAP FROM GROUND TO FIRST BRANCHES
- 7. 3"-6" MULCH / BY NEED PREVENTATIVE TREATMENT
- 8. 3"-4" SAUCE
- 9. REMOVE BURLAP FROM TOP OF ROOT BALL
- 10. BACKFILL WITH 2/3 TOP SOIL, 1/3 SUBSOIL IN 4"-6" LAYERS, WATER LAYER LATER SETTLED
- 11. 3"-12" HARDWOOD STAKES
- 12. 6" MIN. BETWEEN BALL & BOTTOM OF HOLE

TREE PLANTING DETAIL

