



NO APPLICABLE DETAILS APPLY. REFER TO SPECIFICATION 3.30 OF THE VIRGINIA EROSION AND SEDIMENT CONTROL HANDBOOK, LATEST EDITION FOR SPECIFIC REQUIREMENTS.


NO APPLICABLE DETAILS APPLY. REFER TO SPECIFICATION 3.35 OF THE VIRGINIA EROSION AND SEDIMENT CONTROL HANDBOOK, LATEST EDITION FOR SPECIFIC REQUIREMENTS.

NO APPLICABLE DETAILS APPLY. REFER TO SPECIFICATION 3.39 OF THE VIRGINIA EROSION AND SEDIMENT CONTROL HANDBOOK, LATEST EDITION FOR SPECIFIC REQUIREMENTS.







JUNCTION SLOT



TERMINAL FOLD NOTE: BLANKET MATTING (B/M) TO BE USED ON ALL SLOPES 3:1 OR STEEPER.

THE FOLLOWING ARE REPRESENTIVE DETAILS FOR THE STATE MINIMUM STANDARDS AND SPECIFICATIONS RELATIVE TO THE PROPOSED PROJECT. THE GENERAL CONTRACTOR SHALL RELY ON THE COMPLETE STANDARD AS INDICATED IN THE VIRGINIA EROSION AND SEDIMENT CONTROL HANDBOOK FOR PROPER INSTALLATION, CONSTRUCTION AND MAINTENANCE OF THE INDIVIDUAL ITEMS REQUIRED BY THESE PLANS OR AS MAY BE REQUIRED BY THE LOCAL GOVERNING AUTHORITY.





www.balzer.cc PLANNERS • ARCHITECTS ENGINEERS • SURVEYORS

1208 Corporate Circle Roanoke, Virginia 24018 Phone: 540/772-9580 FAX: 540/772-8050

601 Branchway Road Richmond, Virginia 23238 Phone: 804/794-0571 FAX: 804/794-2635

680 Technology Park Drive Suite 200 Glen Allen, Virginia 23059 Phone: 804/553-0132 FAX: 804/553-0133

448 Peppars Ferry Road, NW Christiansburg, Virginia 24073 Phone: 540/381-4280 FAX: 540/381-4291

1581 Commerce Road Suite 401 Verona, Virginia 24482 Phone: 540/248-3220 FAX: 540/248-3221

> ంర EROSION

DESIGNED BY: JVJ CHECKED BY: SMH DATE: 11/14/2007 **REVISIONS:**

> 1st - 01/18/2008 per City Review

SHEET NO.

JOB NO. R0700194.00