





1. REFER TO SHEET C-1 FOR GENERAL NOTES AND LEGEND.




O-RING JOINT DETAIL
 NO SCALE



5
C5 C5

MANHOLE STEP
NO SCALE

